#### Drilling/Sampling Plan for Subsurface Potential PCB Contamination Mahoningside Power Plant Site Warren, Trumbull County, Ohio

### **Drill Locations/Accessibility:**

US EPA RECORDS CENTER REGION 5

U.S. EPA has tentatively identified up to 20 locations which will be selected as drilling points. Determining factors utilized to select locations include, but are not limited to; ability to maneuver the drill rig into position, known locations of contamination, suspected areas of contamination, safety of drill rig placement, and physical observations of the site. Of the proposed sample locations, 6 to 7 have been selected from the surface area surrounding the existing facility structure. Two of these will be to the west, two to the south, two to the east of the facility structure, and one to the north (if possible). The remaining proposed locations will be augured/cored through the cement pad in the former facility's basement.

#### **Drilling Procedures:**

The drill rig will be set up and checked for safety by the operator. It is anticipated that the drilling operations will be two-phased. The first several feet of material under the concrete will be augured until refusal. Once refusal has occurred, then the remaining section of material to be extracted will be cored. This will occur to the sandstone underlaying the shale or to a maximum depth below the concrete surface of twenty feet. The core will then be removed for sampling preparation.

### Sampling of Cuttings/Cores:

The auguring of the first layer in each drilling location is expected to be conducted for the first three to five feet of each hole. The cuttings from auguring activities will be collected from both the top ½ and bottom ½ of the auguring core. These cuttings will each be prepared separately as samples and sent to an independent laboratory for PCB analysis. The core retained will also be processed and split into definitive sections for sample collection. There will be four samples removed from each core. The first sample section will be the top two feet of the core. The second section will be the next three feet of the core. The two final sections, continuing down the core profile, will each be five feet in length. Each section of rock from the core (as listed above) will be pulverized by START and composited. A four-ounce sample will be collected of this material, for each core section, and sent to an independent laboratory for PCB analysis. START will log the physical appearance, rock type, odors, and any other core information deemed necessary. The soil samples for the 6 to 7 drill locations outside of the basement area will be utilized primarily for field screening for the presence of PCBs. At the discretion of the U.S. EPA, samples from these areas may be sent for laboratory analysis of PCB content.

## ERRS REGION V WORK PLAN Contract No. 68-S5-9801

Site Name: Mohning River Site	
Prepared by:	Date:
Preplanning Meeting Date: Oct 4, 2000	Attendees: ERIC BOWMAN, Mark Durno
PART 1. SITE INFORMATION AND BACKGE	ROUND
Task Order No.: 9801-05-	EPA Site No.:
Site Address: 650 Summit Street N.W.	, WARREN, Ohio
EPA FOSC: MARK DUNNO	Office No.: (440) 250-1743
Site Telephone No.:	
Site Background and Description:	
A. Type of Site: PCB contamination IN a of a former electrical power general	nd around the basement foundation
B. History of Site and Type of Activities: Developed	ed Since the early 1900's as Amelectric
power generation plant. Operating und	
Also Electric bulb's and lamps wer	re manufactured here during early
	· · · · · · · · · · · · · · · · · · ·
C. Wastes on Site (chemical names, amount of spill, lagoons, etc.):	no. of drums, no./vol. tanks, no./size
PCB's, Levels of Barium that hazordous WASte	May exceed TCIP levels for
D. Description of Site Physical Features: (acreage, b	uildings, surrounding population, etc.):
The site is Apx 6.58 Acres, with all long	je structures removed. However
the basement power plant and boiler he by the Mahoning River and City parks	
by the Mahoning River and City parks	

E. Site Facilities: Electricity, running water, telephone: Electricity, Telephone
PART 2. SCOPE OF WORK AND APPROACH
2.1 Tasks
Mobilization: Mobe crew and equipment, Spot/Sct Office trailer for EPA
provide Copier, and Fax
Site Logistics: Entry:
Security: Utilize local security Company to perform security during NON-wor
Security: Utilize local Security Company to perform Security during NON-wor how Office Trailer: Acot existing trailer from McCabe Engineering, Rent 2nd trailer for EPA
Decon Area: DRy Decon W/ Trash Cans and disposable PPE
Other:
Initial Containment/Control: Take over operation of Existing treatment system
Primary Cleanup Activities: Collect 2 composite sample from Staged Rolloffs
Annlyze for PCB, TCLP Metals Total Mercury. Collect Samples from Sumps
Analyze for PCB's (Text Metall), Remove Sediment & Cleam 42" discharge
line to River, devoter sediment for disposal. Jet/yac sump and
flow drains throughout basement, demoter sediment for disposal.
Over pack 5 gal bucket containing Mercury/Sediment. Take over Water treatment plaint. Conduct An extent of contamination study to determine extent of PCB's. Alemore/Remediate DCB contamination pending results of the study.
pending results of the study.

Onsite Treatment: Take over operation of existing WWTP. Evaluate
up grades to plant to improve operations. Also Winterize system.
The system will be needed to Not only handle grow
Onsite Waste Staging/Management: <u>Currently 40 Relloffs on 5 ite</u> w/ Sedimento Funtame waste Recovered will need to be
Waste Transportation and Disposal: Existing full boxes at site comencement will most likely be transported by the box owners McCabe Engineering to Model City, MY.
Sampling and Analysis: <u>Collect Samples From Rollofts</u> , <u>Sumps 11 trally</u> this will be followed by an' extent of investigation study:
Reporting: EPA Form 1900-55's, CERCLA Offsite Disposal Report, Contractor's Final Site
Report, Site Safety Plan, Daily Work Report, Site Progress Report, Special Reports (as
specified).
2.2 Key Personnel and Responsibilities
EQ Response Coordinator: John Mullanc Office No.: 800/500-0575
Lead Team Contractor: Office No.:
Response Manager: EAIL BOWMEN

Health and Safety Officer - EQ:	Gene Koest	ers
Health and Safety Officer - Subcontractor		
QA/QC Officer - EQ:	Julie Fields	
QA/QC Officer - Subcontractor:		
<ul><li>2.3 Resource Requirements</li><li>A. Personnel, Equipment, Materials, and</li></ul>	Other Direct Costs (se	e Attachment No. 1)
PART 3. SCHEDULE		
3.1 See Figure 1 for timeline chart		
3.2 Milestones		
<u>Task</u>	Start Date	Completion Date
Initial D.O. Notification:		
Preplanning Visit:	10/4/2000	
Receipt of D.O.:		
Planning and Resource Coordination:		· ·
Mobilization:	10/9	
Cleanup Activity:	10/10	
Waste Sampling/Profiling:		
Drum Removal/Staging:		
Waste T&D:		,———
Demobilization:		

PART 4. BUDGET ALLOCATIO	N
A. D.O. Ceiling:	\$
Estimated Labor:	\$
Estimated Equipment:	\$
Estimated Material:	\$
Estimated T&D and Analysis:	\$
PART 5. HEALTH AND SAFETY	· •
Special Safety Considerations:den	nolition site with Numerous holes and pits
	ver, but still have void space
PPE Requirements: Meditiel D	jand Level C
Site Safety Plan (SSP) Development:	
• Draft SSP submitted in EQ	FO EGE ON 10/4/2000;
Date:	
<ul> <li>Final SSP Plan completed by</li> </ul>	y;
Date:	
PART 6. SAMPLING, ANALYSIS	S, AND QA/QC
A. Site Characterization S & A:	
Sampling & Analysis: _ Will Co	induct an extent of contamination study
to determine further S	
QA/QC Requirements: <u>PA D</u>	

B. Confirmation S&A:	
Sampling & Analysis:	
QA/QC Requirements:	
C. Waste Management/Profiling S&A: Collection (2) composite	Samples
	\$.
9	
PART 7. REGULATORY COMPLIANCE	
Site Permits:	
T&D Status:	
Too otatas.	
	<del></del>
Other:	
FOSC Review/Approval	Date

EQMI CINCINNATI

σ σ	ERRS ACTIVITIES
,	Month/Day/Year

- PROPOSED TIMELINE/SCHEDULE FOR ERRS ACTIVITEPA Contract No. 68-S5-9801, Task Order No. 006

								Extent of contamination Study	Roll off Box Shinwest Edisposal	Misc Jums and Pipeling Cleaning	Sump Sampling	WTP Operation	42" Pipeline Cleaning	Roll off Box Sampling	Melineate Work Zones	Establish Com Post/Support Zone	Mobilization.	ACTIVITIES	
		,																	
-												-							
-	_	$\vdash$		_					_			-	-					$\vdash$	
	_	_	_	_									-					H	
													_						
														А.					
F																			
-	-	-	_			_												П	
-	-	-	_	-									-					H	
-	_	-		-	-				,			_	-					Н	
	_		_	_				_	1									$\vdash$	
	_	_	_		_		_						-					$\vdash$	
																		_	
												,							

\_\_\_\_\_Site

# ATTACHMENT 1 WORK PLAN RESOURCE LIST EPA Contract No. 68-S5-9801 Task Order No. \_\_\_

PERSONNEL (CLIN) On-Site Labor	-		Rate/ST	Rate/OT
(	)			
	)			
(	)			
	)			-
	_)			
Off-Site Labor			Rate/ST	Rate/OT
(	_)	*		
(	_)			
	)			
EQUIPMENT (CLIN)			Ho	urly Rate
()			-	
()			-	
()			٠ .	
()			, .	
()			-	
( )				

†

OTHER DIRECT COSTS (Materials, Rental Equ	uipment, Services, Subs) Price/Unit Price
	•
OTHER DIRECT COSTS (Travel)	Price/Unit Price
Lodging	\$/day
Per Diem	\$/day
* All items provided by EQ unless denoted wit  Denotes provisional rate item.	h asterisk; then item provided by team subcontractor